

HP 34401A Multimeter

- 6 1/2 digit, high performance digital multimeter
- AC/DC voltage measurements
- AC/DC current measurements
- 2 and 4 wire resistance measurements
- Frequency and Period measurements
- Math functions

Safety Tips

**Protect Yourself:
Avoid contact with Voltage or Current
Source.**

- 1) Use shrouded test leads and alligator clips.
- 2) Connect leads to multimeter first.
- 3) Do all normal connect/disconnect at source.
- 4) Familiarize yourself with the manual.

Protect Instrument


- 1) Inductive Devices (e.g. transformers, chokes/inductors) induce very high transient voltages.
- 2) Measuring resistance: Avoid contacting probes with live circuits when in resistance modes.
- 3) Measuring Current: Do not connect probes across voltage source.

Starting Multimeter


- *To perform a complete self-test, hold down the shift key for more than five seconds as you turn on the multimeter.*
- *The display will indicate whether test passed. Error messages will be displayed if a failure occurs.*

000.002 mVDC


Measuring ACV




Measuring DCV




Measuring CURRENT



Measuring Resistance Two-Wire Technique




Measuring Resistance Four-Wire Technique



* Turn off "Null"
 ** "Terminals" switch in "FRONT"
 * Press 4W
 * Voltage is now sensed directly at the resistor, so lead resistance is not a factor

* Because input impedance of DC Input Amplifier is so high, no current flows through sense leads, hence no lead resistance error


4-Wire Resistor Measurement



$$\Delta V = I_{test} * R$$

$$R = \frac{\Delta V}{I_{test}}$$

Continuity Test & Diode Check




Cont = Continuity test

Shift ▶ = Diode check

Measuring Frequency & Period


33.000,0 kHz



Freq = Measure Frequency

Shift Period = Measure Period

Frequency and Period




Period

$$\text{Frequency} = 1/\text{Period}$$

Ratio Measurements

DCV : DCV



$$\text{Ratio} = \frac{\text{dc signal voltage}}{\text{dc reference voltage}}$$

*To enable ratio measurements, use the MEAS menu.

Range and Resolution

<u>Range</u>	100 mV	1 V	10 V	100 V	1000 V (750 VAC)
<u>Maximum Resolution</u>	100 nV	1 μ V	10 μ V	100 μ V	1 mV (750 μ VAC)

Resolution Choices & Integration Time

Integration Time** Resolution Choices

	.02	PLC	Fast 4 Digit	Fastest, Least Accurate
	.2	PLC	Fast 5 Digit	
	1	PLC	* Slow 4 Digit	Slowest, Most Accurate
Default →	10	PLC	* Slow 5 Digit	
	100	PLC	* Fast 6 Digit	
	100	PLC	Slow 6 Digit	

* Equivalent to Pressing "Digits" key on front panel.

**In Power Line Cycles (PLC).

Integration times of .02 and .2 do not provide power-line noise rejection characteristics.

RMS: Root-Mean-Square


* RMS is a measure of a signal's average power. Instantaneous power delivered to a resistor is: $P = [v(t)]^2/R$. To get average power, integrate and divide by the period:

$$P_{avg} = \frac{1}{R} \left(\frac{1}{T} \int_{t_0}^{t_0+T} [v^2(t)] dt \right) = \frac{(V_{rms})^2}{R}$$

Solving for V_{rms} : $V_{rms} = \sqrt{\left(\frac{1}{T} \int_{t_0}^{t_0+T} [v^2(t)] dt \right)}$


* An AC voltage with a given RMS value has the same heating (power) effect as a DC voltage with that same value.

* All the following voltage waveforms have the same RMS value, and should indicate 1.000 VAC on an rms meter:




Measurement Principle: Integrating A/D

- 1) Converts voltage to time to digits
- 2) Integrator is a line-frequency filter
- 3) Integrator is a low-pass filter



Integrator:

$$V_{out} = -\frac{1}{C} \int_0^T i(t) dt$$




If $R1=R2$ $\Rightarrow \int_0^T Vx dt = -Vref dt \Rightarrow T \cdot Vx = To \cdot (-Vref) \Rightarrow \frac{Vx}{-Vref} = \frac{To}{T}$

T is fixed at one cycle of 50 Hz or 60 Hz to eliminate line noise; Vref is fixed; R, C and Time are all ratioed, so accuracy is excellent.


AC-Coupling vs. DC-Coupling

AC-Coupling-Advantage



*Removes DC Portion of Signal


AC-Coupling-Disadvantage



*Low Frequency waveforms can be cut-off

Voltage measurements

Peak to Peak



$$V_{rms} = V_p \cdot .707 \text{ (Sine wave)}$$

The DIGITAL MULTIMETER


Hints for Accurate Measurements:

- Measure as near full scale as possible
- Use a Ratio measurement whenever possible.
- Before measuring, short the test leads together to check for offsets.
(Exception: RMS AC measurements)

Advanced Functions & Measurement Principles

Menu at a Glance

Menu is organized in a top-down tree structure with 3 levels



Math Functions

To make null (relative) measurement **Null**

To store min/max readings **Min Max**

To make dB measurements **Shift** **dB**
 $dB = \text{reading in dBm} - \text{relative value in dBm}$

To make dBm measurements **Shift** **dBm**
 $dBm = 10 \cdot \log_{10} (\text{reading}^2 / \text{reference resistance} / 1mW)$

Limit testing (Access through Menu)

Triggering


Auto-trigger: Continuously takes readings at fastest rate possible for present configuration. Default.

Single trigger: Manual trigger by pressing **Single**
One reading or specified number of readings (Sample count).

Number of samples: Number of readings meter takes with each trigger: 1 to 50,000. Default is 1.

Reading hold: Select by pressing **Shift Auto/Hold**
Captures and holds a stable reading on the display.


High Z Termination



$$V_s = \left(1 + \frac{R_o}{Z_{in}}\right) * V_m \quad \dots \text{ for very large } Z_{in}, V_s \cong V_m$$

As frequency increases, Z_{in} decreases
For less than 1% error $Z_{in} \geq 100 R_o$

50Ω Termination




$$V_s = \left(1 + \frac{50\Omega}{50\Omega}\right) * V_m$$

$$V_s = 2 * V_m$$

$$V_m = \left(\frac{1}{2}\right) * V_s$$

* V_m will not equal V_s , if $Z_{in} = R_o$, but the ratio between them is 2:1.


Loading Errors (DC volts)



V_s = ideal DUT voltage
 R_s = DUT source resistance
 R_i = multimeter input resistance
 (10 MΩ or > 10 GΩ)


$$\text{Error(\%)} = \frac{100 * R_s}{R_s + R_i}$$

Leakage Current Errors



I_b = multimeter bias current
 R_s = DUT source resistance
 C_i = multimeter input capacitance
 $\text{Error}(v) \cong I_b * R_s$

Common Mode Rejection (CMR)



V_f = float voltage
 R_s = DUT source resistance imbalance
 R_i = multimeter isolation resistance

$$\text{Error}(v) = \frac{V_f * R_s}{R_s + R_i}$$